Ohio EPA - Daily Discharge Monitoring Report - Form 4500

SUBMISSION ID:

FACILITY:

LOCATION:

COUNTY: DISTRICT: 118044

American Energy Corp - Century Mine 43521 Mayhugh Hill Rd Twp Hwy 88 Beallsville, OH 43716 Belmont

SEDO

STATUS:

Original

PERMIT NUMBER:

OILOOO91*GD

STATION CODE: MONITORING PERIOD: REPORTING LAB:

2010-07-01 To: 2010-07-31

ANALYST:

NO DISCHARGE INDICATOR: AL

PARAMETER	Sludge Solids,	Sludge Volume,						
PARAMETER CODE	Percent Total 70318	Gallons 80991	<u> </u>	<u> </u>				<u> </u>
UNITS	70318	Gals		\ 				
FREQUENCY	1/Month	1/Month						
SAMPLING TYPE	Grab	Total						
2010-07-01			<u> </u>	<u> </u>				
2010-07-02	<u> </u>		<u> </u>					
2010-07-03								
2010-07-04								
2010-07-05			<u> </u>	<u> </u>				
2010-07-06			<u> </u>	<u> </u>				
2010-07-07								
2010-07-08								
2010-07-09								
2010-07-10								
2010-07-11	L							
2010-07-12								
2010-07-13								
2010-07-14						·		
2010-07-15								
2010-07-16								
2010-07-17								
2010-07-18								
2010-07-19								
2010-07-20								
2010-07-21								
2010-07-22								
2010-07-23								
2010-07-24								
2010-07-25								
2010-07-26								
2010-07-27								
2010-07-28								
2010-07-29								
2010-07-30						Ì		
2010-07-31						Î		· , · · ·
Minimum		11						
Maximum								
Average					<u> </u>			
Count Name of Responsible Official	 	uniter of larget - 1 to	on and live and the state of th	low for its	Signat	ture of Responsible	Official or Authorized	Submission
or Authorized Representative	with the information s	alty of law that I have p submitted herein and bas	sed on my inquiry of the	se	o i guat	Represen	tative	Date/Time
Cody Mozena	individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment. Carly m, Magazar						2010-08- 12 14:08	
Page 17								